













# Structurally Deficient Bridges on the National Highway System


42nd Congressional District of California, 2003



	Structure Number	Road	Location
1	53 2150L	S57/60 SEP	07-LA-057-R4.51-DMBR
2	55 0482	STATE ROUTE 57	12-ORA-057-20.61-BRE

## Legend

-  Structurally Deficient Bridges
-  Interstate Highways
-  California District 42
-  Cities
-  State Highways
-  Amtrak Routes
-  Airports
-  Other Rail Lines
-  Urbanized Areas
-  Navigable Waterways
-  Military Bases
-  Amtrak Stations



U.S. Department of Transportation  
Bureau of Transportation Statistics  
Federal Highway Administration

The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,643 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.